



Dart Aerospace Ltd.  
1270 Aberdeen St  
Hawkesbury, ON  
K6A 1K7  
Canada

Tel (613) 632-5200  
Fax 613 632-5246

## ENGINEERING CHANGE REQUEST

### ECR 130

<b>Date Opened:</b>	1/4/21 11:21 AM	<b>Requested By:</b>	Bellavance, Marc
<b>Type:</b>	Drawing/Pattern Change	<b>Responsible Engineer:</b>	Drouin, Steven
<b>Priority:</b>	Critical	<b>Requester*:</b>	Bellavance, Marc
<b>Status:</b>	Under Review	<b>DM:</b>	Provencal, Chris
<b>Reason:</b>	The FWD D-ring on the liner (LH and RH) conflicts with the OEM baggage door hinge. To eliminate the interference, the D-ring must be moved further aft.	<b>DE Approver*:</b>	Shepherd, David
<b>Expense:</b>	1200	<b>ECR Lead*:</b>	Drouin, Steven
<b>Target Date:</b>	1/8/21 12:00 AM		
<b>Execution Date:</b>			
<b>ECR Approval No:</b>			
<b>RE (R&amp;D):</b>		<b>**BRIEF DESCRIPTION**:</b>	<b>D139-1012 Cargo Net - DSI Needed</b>
<b>Status Note:</b>		<b>DESCRIPTION/ ADR CONTENT**:</b>	DSI needed to address interference of D-ring with OEM baggage door hinge. Move the D-ring to FWD direction to 2 inch to move away from Hinge.

### CUSTOMER APPROVALS

Customer	Customer Visible	Customer Approval Required	*	Customer Approved
CGULF01				

### ATTACHMENT PAGES

Document Name	Document Note
RE_ GULF HELICOPTERS---DART CARGO NET.msg	
A7 -GHM - BAGGAGE DOOR.doc	

### PARTS

[https://www.plexonline.com/f23c67bf-3ef3-4411-9bd8-6fd8436dabd1/Plexus\\_Control/Report\\_View/Viewer\\_2.asp?URL=../ecr/ecr\\_print.asp&ECR\\_Key=2074...](https://www.plexonline.com/f23c67bf-3ef3-4411-9bd8-6fd8436dabd1/Plexus_Control/Report_View/Viewer_2.asp?URL=../ecr/ecr_print.asp&ECR_Key=2074...) 2/2